Wood Destroying Insect Inspection Report Notice: Please read important consumer information on page 2.					
Section I. General Information	September 1981 September 1981 September 1982 September 1982 September 1983 Septem	Company's Business Lic. No. Date of Inspection			
Inspection Company, Address & Phone	BU-3726		06/21/17		
Modern Exterminating & Termite 2200 MacDade Blvd	Address of Property Inspe		<u>-l</u>		
P.O. BOX 91	BOB & MAI	RY REEDER			
Holmes, PA 19043 610-586-5525	421 Round Saint David	d Hill Rd ds, PA 19087-4	4737		
Inspector's Name, Signature & Certification, Registration, or Lic. #	!	Structure(s) in	spected		
Scott Kerr #85	50850	HOUSE			
Section II. Inspection Findings This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:					
A. No visible evidence of wood destroying insects was observed.					
B. Visible evidence of wood destroying insects was observed as follows:					
1. Live insects (description and location):					
X 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location): SHELTER TUBES FRONT SILL PLATE					
X 3. Visible damage from wood destroying insects was noted as follows (description and location): FRONT SILL PLATE					
Yes No X It appears that the structure(s) or a portion thereof may The inspecting company can give no assurances with regard to work done by other on treatment and any warranty or service agreement which may be in place. Section III. Recommendations No treatment recommended: (Explain if Box B in Section II is checked) Recommend treatment for the control of: TERMITES			·		
Section IV. Obstructions and inaccessible Areas The following areas of the structure(s) inspected were obstructed or inaccessible:			The inspector may write		
The following areas of the structure(s) inspected were obstructed or inaccessible:		-	or use the following opt 1. Fixed celling	nonarkey: 13. Only visual access	
X Basement 2,3,4,5,0,7,5			2. Suspended ceiling	14. Cluttered condition	
X Crawspace 5				15. Standing water 16. Dense vegetation	
X Attic 5,11			5. Insulation	17. Extenor siding	
X Garage 1,3,6,7			 Cabinets or shelving Stored items 	18. Window well covers 19. Wood pile	
Exterior			8. Furnishings	20. Snow	
Porch			10. No access or entry	21. Unsafe conditions 22. Rigid foam board	
Addition			11. Limited access	23. Synthetic stucco	
Other —			12. No access beneath	23. Synthetic stucco 24. Duct work, plumbing and/or wiring	
Section V. Additional Comments and Attachments (these are an integral part of the report) \$1,325.00 PAID \$1,325.00 CK# 710. TREATED FOR TERMITES ON THURSDAY 07/13/2017, ONE YEAR WARRANTY FOR TERMITES AFTER TREATMENT. WARRANTY IS FULLY TRANSFERABLE TO NEW OWNER, NEW OWNER SHOULD CONTACT MODERN EXTERMINATING TO					
UPDATE THEIR INFORMATION.					
Attachments		, 1,			
Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage, repair, and treatment history has been disclosed to the buyer.		Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.			
x	\ \ \	X			

TERMITE INSPECTION REPORT & QUOTATION

2200 MAC DADE BOULEVARD HOLMES, PENNSYLVANIA 19043

EXTERMINATING & TERMITE CONTROL CO., INC.

(610) 586-5525 (610) 259-6622 FAX: (610) 586-0244 (610) 356-6080 OWNER OR AGENT /5 4 0 9 4				
Bus, Many Readen Date 6/21/1	7 Inspector S/< 93 16 47 Time M 16 47 Requested by			
421 Rooms Nu PI Insp. Date 660 2	93 /097 TimeM			
INSPECTION AT (IF DIFFERENT FROM ABOVE) Phone Phone	Requested by			
WE HAVE ON THIS DATE COMPLETED AN INSPECTION OF THE STRUCTURE(S) INDICATED ABOUT THE STRUCTURE (S) INDICATED	OVE. OUR FINDINGS ARE AS			
☐ Swarmers ☐ Workers ☐ Damage ☐ Tubing ☐ Evidence of old termite ☐ Live termites now active in structure. ☐ Live termites now active ☐ Damage resulting from termites found; ☐ Medium ☐ Extensive ☐ OTHER FINDINGS:	e in debris under struc.			
WE RECOMMEND:				
No termite treatment necessary at this time. Should be treated for the	e prevention of termites.			
We propose to chemically treat this structure(s) with our chemical formulations in accordance witions and guarantees as follows:	th our standard specifica-			
Drill all concrete resting against foundation walls and chemicalize soil beneath. As we proceed with this wor parts not mentioned in this !	k and we find any vulnerable etter, we will treat same.			
Chemicalize all soil Testing against foundation walls All holes to be sealed with co	ement '			
Enound outside of house This work guaranteed for	14 con			
Drill inside perimeter of garage floor and chemicalize soil beneath. Drill inside perimeter of garage floor and chemicalize soil beneath. After the year period and treat any reinfestation at year if desired. Yearly warrant	od, we will inspect yearly t a charge of <u>1500</u> per ntee subject to change due			
Drill inside perimeter of basement floor and chemicalize soil beneath.	rispace.			
STRUCTURAL LAYOUT NOT DRAYN TO SCALE LEGEND Termite 11111 Damage XXXXX Notes: Annual A				
QUOTATION CHEMICAL TREATMENT Including Guarantee	\$ 1250.			
TERMS:	Tex 7500 Total 4335,00			
This proposal covers only the work itemized. The price quoted includes labor, materials, transportation, insurance and guarantee. All work will be covered by workman's compensation and public liability insurance. The job will be started within days weather conditions permitting. Payment to be made as follows				
I hereby certify this inspection was made in a thorough manner and is true and correct insofar as v				
ACCEPTED BY OWNER/AGENT: Signed M/a Signed	sof Kenninspector			