

## Radon Inspection Report

**Test Location:**

Agnes Warren POA for Eva Garami  
132 Hillside Rd  
Wayne, PA 19087

**Test For:**

Agnes Warren POA for Eva Garami  
132 Hillside Rd  
Wayne, PA 19087

**Inspected By:**

PO Box 33450  
Philadelphia, PA 19142  
215 778 7118  
Lic/Cert. # PA 2590

### Test Result: Pass

EPA Average:

1.7 pCi/l

**Test Device Details:**

Serial Number: 259926011  
Model Number: 1028XP  
Last Calibration: 11/15/2023  
Next Calibration: 11/15/2024  
Cal-Factors: 2.52  
Motion Error: Yes

**Test Site Condition:**

Condition: Recent Rainfall  
Structure Type: Single home  
Mitigation Sys: Not Installed

**Test Summary:**

| <u>CRM Location:</u>          | <u>Start:</u>          | <u>Stop:</u>           | <u>Interval:</u> | <u>Duration:</u>          |
|-------------------------------|------------------------|------------------------|------------------|---------------------------|
| Above crawl                   | 03/27/2024<br>09:56 AM | 03/29/2024<br>09:56 AM | 1 hr             | 48 hr                     |
| *First 4 hrs of data excluded | <u>Min:</u>            | <u>Max:</u>            | <u>Average:</u>  | <u>Measurement Units:</u> |
| Radon Concentration:          | 0.0                    | 4.4                    | 1.7              | pCi/l                     |

**Comments:**

No tampering evident. Crawl vent position: NA Authorization agreement: unsigned. Monitor placed by: PA 8883 Kalin Monitor retrieved by: PA 8701 Lerro

  
Lic/Cert Signature

Inspection Report Date: 03/30/2024